

04-05-226828

PLEASE PRINT

## State of Wisconsin Substance Release Notification Form

Your Emergency Hotline Number: 1-800-943-0003

Form 4400-91 Rev. 11-95

Date and Mil. Time of Incident 06:00 9/3/98 9.3.98 Date and Mil. Time Reported 08:20 9/3/98

Person Reporting Kathy Nelson Telephone # (920) 433-5011

Representing Agency, Firm, or Citizen Green Bay Packaging Inc (GBPI)

Responsible Party GBPI

Contact Name Kathy Nelson Telephone # (920) 433-5011

Address 1601 N. Quincy Street City, State, Zip Code Green Bay, WI 54307  
P.O. Box 19617

Substance Involved Process Water Amount & Units Released ~3000 Gallons Amt. Recovered \_\_\_\_\_ Is this a 304 (11004 42 USC) spill?  
☐ Yes ☐ No ☐ Unknown

☐ Solid ☐ Semisolid ☒ Liquid ☐ Gas Color Brown Odor \_\_\_\_\_

Exact Location (inc. address, facility name, mileage, bldg. #, etc.) ~~1601 N. Quincy~~ 1601 N. Quincy, on the SE side of 2 tanks west of mill building

City Green Bay County Brown Lat/long \_\_\_\_\_

DNR Region NE 1/4 1/4sec T NR (E/W) Weather Cond. \_\_\_\_\_

Cause of Incident Drain valve had been left open ~~when~~ when process water was being transferred. This water then overflowed the pump room between the 2 tanks and flowed on the ground surface.

<b>Spilled Substance Impact To:</b> Check (✓) all that apply <input type="checkbox"/> Air <input type="checkbox"/> Potential <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Potential <input checked="" type="checkbox"/> Groundwater <input checked="" type="checkbox"/> Potential <input type="checkbox"/> Surface Water <input type="checkbox"/> Potential Name: _____ <input type="checkbox"/> Storm Sewer <input type="checkbox"/> Potential <input type="checkbox"/> Sanitary Sewer <input type="checkbox"/> Potential <input type="checkbox"/> Concrete/Asphalt <input type="checkbox"/> Potential <input type="checkbox"/> Private Well <input type="checkbox"/> Potential <input checked="" type="checkbox"/> Contained/Recovered <input type="checkbox"/> Other: _____	<b>Spill Source:</b> <input type="checkbox"/> Transportation Accident, Fuel Supply Tank Spill <input type="checkbox"/> Transportation Accident, Load Spill <input checked="" type="checkbox"/> Industrial Facility <input checked="" type="checkbox"/> Paper Mill <input type="checkbox"/> Chemical Co. <input type="checkbox"/> Ag Coop/Facility/Food Factory/Facility <input type="checkbox"/> Gas/Service Station/Garage/Auto Dealer, Repair Shop <input type="checkbox"/> Pipeline, Terminal, Tank Farm, Oil Jobber/Wholesaler <input type="checkbox"/> Public Property (city, state, church, school, etc.) <input type="checkbox"/> Utility Co., Power Generating/Transfer Facility <input type="checkbox"/> Private Property (home/farm) <input type="checkbox"/> Construction, Excavation, Wrecking, Quarry, Mine <input type="checkbox"/> Airport Facility <input type="checkbox"/> Railroad Facility <input type="checkbox"/> Other: _____	<b>Action Taken By Spiller</b> <input type="checkbox"/> No Action Taken <input type="checkbox"/> No Action Needed <input checked="" type="checkbox"/> Monitor <input checked="" type="checkbox"/> Cleanup Method: _____ <input type="checkbox"/> Waste Destination: _____ <input type="checkbox"/> Containment <input type="checkbox"/> Contractor Hired Name: _____ <input type="checkbox"/> Other: _____
---	---	---

Injuries? ☐ Yes ☒ No If yes, how many? \_\_\_\_\_ Has an evacuation occurred? ☐ Yes ☒ No Potential? ☐ Yes ☐ No

Are there any resource damages? ☐ Yes ☐ No ☒ Potential What kinds? Groundwater contamination

<b>Other Agencies Notified (✓ first column if notified); Check (✓) both columns if on scene</b> <input type="checkbox"/> Fire Department/Hazmat <input checked="" type="checkbox"/> Local DNR <input type="checkbox"/> EPA <input type="checkbox"/> Local Law Enforcement <input type="checkbox"/> Div. Emer. Gov. <input type="checkbox"/> Nat'l Resp. Ctr. 800-442-8802 <input type="checkbox"/> LEPC or Local Emer. Gov. <input type="checkbox"/> DATCP 608-224-4500 <input type="checkbox"/> Chemtrec 800-424-9300 <input type="checkbox"/> Regional Response Team <input type="checkbox"/> DHSS 608-266-2830 <input type="checkbox"/> Other: _____	Incident Commander, if known: _____ Phone: _____
---	---

Prepared By: (Print) Jeffrey J. Haack (Sign) [Signature] Date: 9/3/98 Rpt'd to DATCP? ☐ Yes ☐ No

Person Notified: \_\_\_\_\_ Region Notified: \_\_\_\_\_ Time: \_\_\_\_\_ Date: \_\_\_\_\_

Invstgtd By: (Print) \_\_\_\_\_ (Sign) \_\_\_\_\_ Date: 9/3/98 Site Closed? ☒ Yes ☐ No

Spill Coordinator Signoff: \_\_\_\_\_ Date: \_\_\_\_\_ Transferred to ERP? ☒ No ☐ Yes; Case # \_\_\_\_\_ NFA Letter Sent? ☐ Yes ☒ No  
my 1 clt 9-30-98 Spill Packet Sent? ☐ Yes ☒ No

☒ Additional Comments on Reverse

State of Wisconsin Substance Release Report (Con't)  
Form 4400-91 Rev. 11-95

Date and Military Time of Incident 9/3/98 06:00

Responsible Party Green Bay Packaging, Inc.

## Additional Comments:

This is the 2nd significant spill of process water at this mill within 2 months. The volume is only a very rough estimate. I was on-site at ~10:00. Some water was still in a small pool (puddle). I advised constructing a small sump at the lowest corner, and getting a vacuum truck to collect any water possible.

I instructed Mr. Nelson to send me a letter detailing: 1) the cause of this spill; 2) clean-up effected; and 3) steps which GBPI will take to prevent future spills. This must be sent by the end of next week.

I advised that enforcement staff will be consulted to ascertain whether any enforcement actions are appropriate.

04-02-98-200  
Guth + Jeff Hunt Meeting GBPI tomorrow  
discuss what to do next

Green Bay Packaging



Inc.

®

• MILL DIVISION

November 17, 1998

Mr. Jeffrey J. Haack, Wastewater Engineer  
Wisconsin Department of Natural Resources  
P. O. Box 10448  
Green Bay, Wisconsin 54307-0448

Dear Jeff:

Re: WPDES Permit No. WI-0000973-6, FID No. 405032100

Enclosed is a copy of the testing we had performed on our process water per your request. The test for formaldehyde was re-sampled because the laboratory exceeded the holding time. Please note that the test results are from process water and not the ground water.

The Yard Process Water Collection System is progressing. The pipe has been laid with the correct pitch. The drains and overflows are being connected as time allows since some of the tanks must be empty before they can be worked on.

Sincerely,

GREEN BAY PACKAGING INC.  
Mill Division

Kathleen A. Nelson  
Environmental Manager

KAN:kn

Enclosures

cc: Brian Duffy  
Orv Rautmann  
Jeffrey Walch  
File



1795 Industrial Drive  
Green Bay, WI 54302  
920-469-2436  
800-7-ENCHEM  
Fax: 920-469-8827

## - Analytical Report -

Project Name : PROCESS WATER ANALYSIS

Project Number :

Client: GREEN BAY PACKAGING INC

WI DNR LAB ID : 405132750

Report Date : 11/6/98

Sample No.	Field ID	Collection Date	Sample No.	Field ID	Collection Date
886051-001	PROCESS WATER	10/12/98			

The "Q" flag is present when a parameter has been detected below the LOQ. This indicates the results are qualified due to the uncertainty of the parameter concentration between the LOD and the LOQ.

Soil VOC detects are corrected for the total solids, unless otherwise noted.

I certify that the data contained in this Final Report has been generated and reviewed in accordance with approved methods and Laboratory Standard Operating Procedure. Exceptions, if any, are discussed in the accompanying sample narrative. Release of this final report is authorized by Laboratory management, as is verified by the following signature.

Ja. Duranseau  
Approval Signature

11/6/98  
Date



1795 Industrial Drive  
Green Bay, WI 54302  
920-469-2436  
800-7-ENCHEM  
Fax: 920-469-8827

TestGroupID:

Comment:

886051-001 M-SE-W

Elevated detection limit due to matrix effects.

PROCESS WATER

W-N-W

Elevated detection limit due to matrix effects.



1795 Industrial Drive  
Green Bay, WI 54302  
920-469-2436  
800-7-ENCHEM  
Fax: 920-469-8827

## - Analytical Report -

Project Name :

Project Number :

WI DNR LAB ID : 405132750

Client: GREEN BAY PACKAGING INC

Report Date : 11/6/98

Sample No.	Field ID	Collection Date	Sample No.	Field ID	Collection Date
886439-001	PROCESS WATER REUSE	10/28/98			

The "Q" flag is present when a parameter has been detected below the LOQ. This indicates the results are qualified due to the uncertainty of the parameter concentration between the LOD and the LOQ.

Soil VOC detects are corrected for the total solids, unless otherwise noted.

I certify that the data contained in this Final Report has been generated and reviewed in accordance with approved methods and Laboratory Standard Operating Procedure. Exceptions, if any, are discussed in the accompanying sample narrative. Release of this final report is authorized by Laboratory management, as is verified by the following signature.

J. Durancean  
Approval Signature

11/6/98  
Date



1795 Industrial Drive  
Green Bay, WI 54302  
920-469-2436  
800-7-ENCHEM  
FAX: 920-469-8827

## - Analytical Report -

Project Name : PROCESS WATER ANALYSIS

Project Number :

Client : GREEN BAY PACKAGING INC

Field ID : PROCESS WATER

Report Date : 11/5/98

Lab Sample Number : 886051-001


Collection Date : 10/12/98

WI DNR LAB ID : 405132750

Matrix Type : WATER

### Inorganic Results

Test	Result	LOD	LOQ	EQL	Units	Code	Analysis Date	Prep Method	Analysis Method	Analyst
Arsenic	< 5.9	5.9	19		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Barium	500	0.26	0.83		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Beryllium	< 0.48	0.48	1.5		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Cadmium	3.4	0.41	1.3		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Chloride	250	1.4	4.5		mg/L		10/26/98	EPA 325.1	EPA 325.1	*MD
Copper	64	1.6	5.1		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Fluoride	0.65	0.075	0.24		mg/L		10/27/98	SM 4500F-C	SM 4500F-C	*MD
Iron	570	34	110		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Lead	16	3.0	9.6		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Manganese	1200	0.41	1.3		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Mercury	attached				ug/L			SW846 7470A	SW846 7470A	*NLS
Nickel	120	2.4	7.6		ug/L		10/29/98	SW846 3010A	SW846 6010B	*MD
Nitrogen, NO3 + NO2	< 0.26	0.26	0.83		mg/L	M	10/29/98	EPA 353.2	EPA 353.2	*MD
Phenolics, total recoverable	1.8	0.21	0.67		mg/L		10/28/98	EPA 420.2	EPA 420.2	*MD
Selenium	4.4	0.67	2.1		ug/L	M	11/2/98	SW846 3015	SW846 7740	*MD
Silver	< 0.43	0.43	1.4		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD
Sulfate	960	20	64		mg/L		10/27/98	EPA 375.2	EPA 375.2	*MD
Zinc	580	3.7	12		ug/L		10/29/98	SW846 3015	SW846 6010B	*MD



**Project Name :**

**Project Number :**

**Client : GREEN BAY PACKAGING INC**

Field ID : PROCESS WATER REUSE

**Report Date : 11/5/98**

**Lab Sample Number : 886439-001**

Collection Date : 10/28/98

WI DNR LAB ID : 405132750

**Matrix Type : WATER**

[illegible]



**LLI Sample No. ww 3028604**

Collected: 10/28/98

Submitted: 10/29/98 Reported: 11/ 4/98  
Discard: 11/19/98

001 Process Water Sample  
Project 886439

Account No: 10149  
En Chem

1241 Bellevue Street  
Green Bay WI 54302

P.O. 886439  
Rel.

CAT NO.	ANALYSIS NAME	AS RECEIVED		
		RESULTS	LIMIT OF QUANTITATION	UNITS
4144	Formaldehyde in Water	< 5,000.	5,000.	ug/l
Due to the nature of the sample matrix, a reduced aliquot was used for analysis. The Limits of Quantitation (LOQ's) were raised accordingly.				

1 COPY TO En Chem

ATTN: Ms. Lori Woelfel

Questions? Contact your Client Services Representative  
Gwen A. Birchall at (717) 656-2300  
09:20:04 D 0001 1 638421  
417 0.00 00035000 ASR000

Respectfully Submitted  
Jenifer E. Hess, B.S.  
Group Leader Pesticides/PCBs



Lancaster Laboratories  
2425 New Holland Pike  
PO Box 11425  
Lancaster, PA 17605-1425  
TEL: 717-656-2300 FAX: 717-656-2301





LLI Sample No. WW 3028604

Collected: 10/28/98

Submitted: 10/29/98

001 Process Water Sample  
Project 886439

001-- SDG#:

Account No: 10149  
En Chem

1241 Bellevue Street  
Green Bay WI 54302

CAT NO	ANALYSIS NAME	METHOD	TRIAL ID	ANALYSIS DATE AND TIME	ANALYST
1013	Formaldehyde Extraction	SW-846 8315A	1	10/30/98 1100	Anita M. Dale
4144	Formaldehyde in Water	SW-846 8315A	1	11/02/98 1058	Michelle J. Kolodziejski



NORTHERN LAKE SERVICE, INC.  
Analytical Laboratory and Environmental Services  
400 North Lake Avenue - Crandon, WI 54520  
Tel:(715)478-2777 Fax:(715)478-3060

WIS. LAB CERT. NO. 721026460

## ANALYTICAL REPORT

PAGE: 1 NLS PROJECT# 44238  
NLS CUST# 87182

Client: En Chem Inc  
Attn: Tom Trainor  
1241 Bellevue Street  
Green Bay, WI 54302

Project Description: Low Level Hg

Sample ID: 001 NLS#: 182191  
COC Description: 001  
Collected: 10/12/98 Received: 10/14/98 Reported: 11/03/98

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>LOD</u>	<u>LOQ</u>	<u>Method</u>	<u>Analyzed Lab</u>
Mercury, Low Level as Hg	110	ng/L	19	76	EPA 245.7M	11/03/98 721026460

Values in brackets represent results greater than the LOD but less than the LOQ and are within a region of "Less-Certain Quantitation".  
Results greater than the LOQ are considered to be in the region of "Certain Quantitation".

LOD = Limit of Detection  
DWB = Dry Weight Basis


LOQ = Limit of Quantitation  
NA = Not Applicable

ND = Not Detected  
%DWB = (mg/kg DWB)/10000

*Steven R. Cugini*  
Reviewed by:

Authorized by:  
R. T. Krueger  
Laboratory Manager

En Chem Project No.	886439
Sample Receipt Temp.	16.5
Sample Receipt pH (Wet/Metals)	
Custody Seal	



36445

ANALYSES REQUESTED

Page \_\_\_\_\_ of \_\_\_\_\_

P.O. #                      Quote #

Mail Report To: Kathy Nelson

Company: Green Bay Packaging

✓ Address: P.O. Box 19017

Green Bay WI 543079017

Invoice To: Green Bay Pk

Company: \_\_\_\_\_  
Address: Same

Mail Invoice To: Linda Lerner

SHADED AREA FOR LABORATORY USE ONLY

## COMMENTS

LABORATORY  
NUMBER

Green Bay Packaging



Inc.

®

• MILL DIVISION

October 20, 1998

Mr. Jeffrey J. Haack, Wastewater Engineer  
Wisconsin Department of Natural Resources  
P. O. Box 10448  
Green Bay, Wisconsin 54307-0448

Dear Jeff:

Re: WPDES Permit No. WI-0000973-6, FID No. 405032100

The Yard Process Water Collection Project that we discussed with you on October 1, 1998 was approved. The material was ordered and construction will begin just prior to the arrival of the material in approximately two weeks. Process water was sent in for analysis and the results are expected back in three weeks. Please call if you would like any further information.

Sincerely,

GREEN BAY PACKAGING INC.  
Mill Division

Kathleen A. Nelson  
Environmental Manager


KAN:kn

Enclosure

cc: Brian Duffy  
Orv Rautmann  
Jeffrey Walch  
File

*(En Chem will not confirm unless otherwise instructed.)*



 1423 N. 8th Street, Suite 122  
Superior, WI 54880  
715-392-5844 • 1-800-837-8238  
FAX 715-392-5843

## CHAIN OF CUSTODY

31692

Page \_\_\_\_\_ of \_\_\_\_\_

P.O. #                      Quote #

Mail Report To: \_\_\_\_\_

Company: \_\_\_\_\_

Address: \_\_\_\_\_

Invoice To: \_\_\_\_\_

Company: \_\_\_\_\_

X Address: \_\_\_\_\_

Mail Invoice To: \_\_\_\_\_

[illegible]

**\*Preservation Code**

**A=None    B=HCL    C=H2SO4**

**D=HN03      E=EnCore      F=Methanol\*\***

G=NaOH O=Other (Indicate)

**\*\*If not using En Chem's methanol, indicate volume of methanol added and mark the appropriate samples.**

Relinquished By: Alan Lawson Date/Time: 10-12-98 16:50

Relinquished By: \_\_\_\_\_ Date/Time: \_\_\_\_\_

Relinquished By: \_\_\_\_\_ Date/Time: \_\_\_\_\_

Relinquished By: \_\_\_\_\_ Date/Time: \_\_\_\_\_

Received By:	Date/Time:
--------------	------------

Received By: \_\_\_\_\_ Date/Time: \_\_\_\_\_

Received By:	Date/Time:
--------------	------------

Received By: \_\_\_\_\_ Date/Time: \_\_\_\_\_

En Chem Project No.

88605

Sample Receipt Temp.	
----------------------	--

**Sample Receipt pH**  
(Wet/Metals)

**Custody Seal**

# CORRESPONDENCE/MEMORANDUM

State of Wisconsin

DATE: October 7, 1998

FILE REF:

TO: Files

FROM: Jeff Haack - Green Bay *JH*

SUBJECT: Green Bay Packaging, Inc. (GBPI)

On Thursday, October 1, 1998, Chris Groth, Brown County Conservation Warden, and I went to the GBPI mill at 1601 N. Quincy Street in Green Bay to investigate and follow up on the recent spills which have occurred at this facility. Jeffrey Walch, Vice President/General Manager, Kathleen Nelson, Environmental Manager, and Brian Duffy, Corporate Environmental Director, participated in this discussion.

I began by characterizing this visit as a fact-finding mission. I advised that the department was very concerned about the fact that there have been three significant spills of process water over the past three months, and that we were considering enforcement actions to address this. I described the following alternatives under consideration: 1) A citation could be issued pursuant to s. 29.29 Stat., for discharging a deleterious substance to waters of the state. Since the volume spilled exceeded the volume recovered, there was apparently a discharge to groundwater, which is considered waters of the state. 2) GBPI could be referred to the Department of Justice for discharging without a permit, pursuant to s. 283.31 Stat. The WPDES permit issued to GBPI authorizes discharge to the Fox River, with appropriate effluent limitations, based upon characterization of the effluent provided in the permit application. 3) Or finally, the department could take no formal enforcement action after being satisfied that GBPI has taken all appropriate actions to prevent further spills of this nature. With either option 1 or 2, the department would also seek court orders to require actions to prevent further spills, in addition to (potential) monetary penalties.

Jeff Walch then described proposed revisions to the "Yard Process Water Collection Piping Layout." This was the second alternative mentioned in the September 24, 1998, letter from Kathy Nelson. These revisions consist of installing a new 24" diameter pipe to collect the drains and overflows from all five storage tanks located outside of the primary mill structure. This new pipe would then drain back into the basement of the mill. Two new catch basins would be installed, and the floor drain in building # 14 (where the pipe fitting failed resulting in the July 17, 1998, spill) would also be connected to this pipe. A drawing showing all of the revisions was provided. Brian Duffy inquired whether these revisions were subject to DNR review and approval requirements, and I responded that they were not. The design work has been completed, but funding has not yet been secured.

Kathy Nelson also described changes in the alarm system, and spill response procedures. With regard to the alarm system, tank overflows or similar alarms, have been switched to a

different system such that it is much more difficult to disregard, as happened with the September 3, 1998, spill. I requested more complete description in writing. With regard to the spill response procedures, several changes have been made. First, these procedures now include spills of the "process water." Previously only specific chemicals used on-site were included. Secondly, the procedures now specify that spilled process water must be cleaned up as soon as possible. And third, the responsibility for spill response has been clearly specified as the responsibility of the shift supervisor.

Chris and I also requested more complete characterization of the process water which had been spilled on these three occasions. This information is requested to evaluate whether some remediation of the "contaminated" soil and groundwater is appropriate. I suggested using NR 140, Wisc. Admin. Code as a guide, reviewing the MSDS sheets for any additives to ascertain substances which may be present, and performing an actual analysis. I advised that I did not foresee a need for analysis of a wide range of organic substances, but expected analysis for a number of inorganic substances for which groundwater standards have been established.

We then proceeded out the area west of the mill, where these three spills had occurred. Jeff Walch did not accompany us during this part of the visit. Chris expressed concern about tank failure, considering the size of several of these tanks and their close proximity to the Fox River. This may simply be a matter of careful attention to the grading of the surface in the area.

We concluded this visit by summarizing the information which was requested: 1) Status report on the yard piping project; 2) Characterization of the process water; 3) Description of changes to the alarm system and spill response procedures; and 4) Addressing the potential for tank failure. I expect that the characterization will require approximately a month to complete, and a single response is requested. Whether any further action by the department is appropriate will be determined following a review of this information.

cc: Chris Groth  
→ Roxanne Chronert Nelezen  
Judy Doelger  
Jeff Brauer - WT/2  
NER Wastewater Files

Green Bay Packaging



Inc.

®

• MILL DIVISION

October 7, 1998

Mr. Jeffrey J. Haack, Wastewater Engineer  
Wisconsin Department of Natural Resources  
P. O. Box 10448  
Green Bay, Wisconsin 54307-0448

Dear Jeff:

Re: WPDES Permit No. WI-0000973-6, FID No. 405032100

We have installed the alarms on the sump pumps in the 250,000 Pump House and the Krofta Pump House to the environmental alarm system. These alarms have a red flashing light hooked up to them so they do not become one of many alarms during down time. I have included the print out from an alarm check on the new alarms.

The alarm write up has been updated to include these alarms. It will probably be updated again after I receive feed back from the employees. A copy of this write up is attached to the alarm print out where the person acknowledges the alarm. The Shift Coordinator, whom is on site 24 hrs. / Day, has been assigned the responsibility to respond to every alarm. I have discussed the alarm procedures and write-up with the Shift Coordinators, Machine Tenders, Back Tenders, and the lab personnel again.

Sincerely,

GREEN BAY PACKAGING INC.  
Mill Division

Kathleen A. Nelson  
Environmental Manager

KAN:kn

cc: Brian Duffy  
Orv Rautmann  
Jeffrey Walch  
File

Alarm Check

KW

FRI OCTOBER 2, 1998  
250 PUMP HOUSE FLOODED

7 : 47 : 3

FRI OCTOBER 2, 1998  
250 PUMP HOUSE NORMAL

7 : 47 : 8

DURATION 0 : 0 : 5

FRI OCTOBER 2, 1998  
250 PUMP HOUSE FLOODED

7 : 47 : 25

FRI OCTOBER 2, 1998  
250 PUMP HOUSE NORMAL

7 : 47 : 27

DURATION 0 : 0 : 2

FRI OCTOBER 2, 1998  
250 PUMP HOUSE NORMAL

7 : 47 : 30

DURATION 0 : 0 : 2

FRI OCTOBER 2, 1998  
KROFTA PUMP HOUSE FLOODED

7 : 51 : 12

FRI OCTOBER 2, 1998  
KROFTA PUMP HOUSE NORMAL

7 : 51 : 19

DURATION 0 : 0 : 7

FRI OCTOBER 2, 1998  
KROFTA PUMP HOUSE NORMAL

7 : 51 : 21

DURATION 0 : 0 : 1